
Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



HARDWARE LIST				
NO	DESCRIPTION		QTY	
A		BOLT M10 X 80	8	
В	0	SPRING WASHER	12	
С	(Communication)	BOLT M10 X 60	4	
D	0	WASHER M10	12	
Е	(1)	NUT M10	12	
F		17mm HEX WRENCH	1	
G	anana	SCREW M4 X 30	32	
Н		BOLT M8-20	1	
I	0	BOLT M8-40	1	
J		NUT M8	1	
K		13mm HEX WRENCH	1	

PARTS LIST					
NO	DESCRIPTION				
1		HEADBOARD	1		
2		FOOTBOARD	1		
3		SIDE RAIL	2		
4		CENTER SUPPORT RAIL	1		
5		SLAT	16		

TYB012.G_KING BED

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

STEP 1

Assemble part (1),(2)&(3)



A:8



D:8




E:8



F:1



B:8



STEP 2

Assemble part (D)



H:1




I:1



J:1



K:1



Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

