
FR006.N\_SIDE TABLE INSTRUCTION SHEET 1/2

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



HARDWARE LIST				
NO	DESCRIPTION QT		QTY	
А		BOLT M8x50	8	
В		SPRING WASHER M8	8	
С	0	WASHER M8	8	
D	~	ALLEN KEY M4x110	1	

PARTS LIST					
NO	DESCRIPTION		QTY		
1		TABLE TOP	1		
2		LEGS	2		
3		BOTTOM FRAME	1		

FR006.N\_SIDE TABLE INSTRUCTION SHEET 2/2

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

