
IONA020_CONSOLE TABLE INSTRUCTION SHEET 1/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.




HARDWARE LIST				
NO	DESCRIPTION		QTY	
А		BOLT M8x60	12	
В		SPRING WASHER M8	10	
С	0	WASHER M8	10	
D		BOLT M8x40	2	
E		ALLEN KEY M4	1	

PART LIST					
NO	DESCRIPT	QTY			
1		TABLE TOP	1		
2		LEGS	2		
3		STRETCHER	1		
4		SUPPORT RAIL	2		

IONA020_CONSOLE TABLE INSTRUCTION SHEET 2/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



IONA020_CONSOLE TABLE INSTRUCTION SHEET 3/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

STEP 3

Assemble part (4)



A:4



