
VNT11_DESK INSTRUCTION SHEET 1/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.




HARDWARE LIST				
NO	DESCRIPTION		QTY	
A		BOLT M8 X 50	12	
В	0	WASHER M8	14	
С		ALLEN KEY M4	1	
D		BOLT M8 X 80	2	
Е		NUT M8	2	
F	5	13mm HEX WRENCH	1	
G	(hommon)	SCREW M 4 x 40	4	
Н	o	SPRING WASHER M8	12	

PARTS LIST					
NO	DESCRIPTION				
1		TABLE TOP	1		
2		LEGS (LEFT-RIGHT)	2		
3		BACK RAIL	1		
4		SUPPORT	2		

VNT11_DESK INSTRUCTION SHEET 2/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.



VNT11_DESK INSTRUCTION SHEET 3/3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

